

[Network](#) | [Serial](#) | [GPIO](#) | [Password](#)

Serial

PORT 0

PORT 1

Data port settings (DEBUG defaults to port 0 if both are set to DEBUG):

Data baud rate:

Custom baud rate:

Data bits:

Stop bits:

Data parity:

Flow control:

Allow AT commands:

AT attention command char:

RS-232 ▼

9600 ▼

0

8 ▼

1 ▼

None ▼

None ▼

☒

43 (+)

RS-232 ▼

9600 ▼

0

8 ▼

1 ▼

None ▼

None ▼

☒

43 (+)

Submit New Settings